

J-11 NONE

J-3X NONE

J-13A DFC DID NOT RECEIVE UNREG VOLTAGE DURING NORMAL OPERATION ON SLAVE.

J-15 NONE

J-18B ERRATIC METERING LAST HALF ON MSN. CONTRIBUTED TO ERRATIC OPERATION OF K-784.

J-17 NONE

J-14A NONE

J-14B ERRATIC METERING THROUGHOUT MISSION, FAULTY METERING SOLENOID. SOLENOID CHANGED JUST PRIOR TO FLIGHT AND ONLY 220 CYCLES RUN PRIOR TO LAUNCH.

- J=19 NBR 3 PROGRAMMER FAILED AFTER 55 CYCLES OF "A" HISSION.

 UNIT SLOWED WHEN COMMANDED. PROBABLE CAUSE: BLOWN FUSE

 IN PROGRAMMER UNITS.
- 3. THE FUSE WHICH APPEARS TO BE THE FAILURE MODE IN THE J-19
 SI EXISTS BECAUSE SI IS A SECONDARY COMPONENT IN THE CORONA SYSTEM,
 AND ALL SECONDARY SYSTEMS ARE FUSED. MAY RECALL THAT AT A MEETING
 IN LOS ANGELES SUGGESTED THAT IF SI WAS TO BE CONSIDERED
 A PRIME REQUIREMENT BECAUSE OF MAPPING MISSION, THAT WE MAY WISH TO RENG
 THIS FUSE. IS EXPLORING THE CONSUMERS SI REQUIREMENT THRU
 AND SYSTEMS INTEGRATION SECTION AT AND LIAISON OFFICER AT
 HAVE BEEN ASKED TO STUDY THE SYSTEMS IMPLICATIONS.
 - 4. REP AT WILL PROVIDE DETAILS OF J-19 AND CTHER FAILURE

SECRET

SEGRET

PAGE THREE

ANALYSIS AT WEXT MONTHLY (SIC) MEETING. IN VIEW OF ANALYSIS PRESENTED ABOVE EFFORTS INCIDENT TO AND DIRECTION SUPPLIED REF B, DESIGN REVIEW CONSIDERED UNWARRANTED AT THIS TIME.

END OF MESSAGE