

24 NOV 1988

1. [REDACTED]
2. [REDACTED]
3. [REDACTED]

~~SECRET~~

C/ [REDACTED]

Copy No. [REDACTED]

17 Sheets

[REDACTED]
14 000227700
[REDACTED]
[REDACTED]

PROGRAM MANAGER'S MEETING
13 NOV. 69

A/P TOPICS:

- o REVIEW OF CR-8 REQUALIFICATION
- o READINESS REVIEW OF CR-9

Declassified and Released by the N R C
In Accordance with E. O. 12958
on NOV 26 1997

~~SECRET~~ C/ [REDACTED]

C/ [REDACTED]

Copy No. [REDACTED]

ASCENT QUALIFICATION TEST
CR-8

OBJECTIVE

- QUALIFY THE UTB MODIFICATIONS INCORPORATED IN THE CR SUBSYSTEM (ASCENT MODE)
 - I/R BOBBLER
 - SUPPLY CASSETTE TENSION SERVO
 - SUPPLY CASSETTE BRAKE LOCKED - NO POWER DURING ASCENT

ASCENT QUALIFICATION TEST
CR-8TEST PLAN

- SYSTEM IN FLIGHT CONFIGURATION EXCEPT DISIC AND TAPE RECORDER SUBSYSTEM NOT INSTALLED
- [REDACTED] SIMULATION - 3.5G, 14 TO 20 1/2 HZ, 35 SECOND DURATION
- ACOUSTIC SIMULATION - 156 DB, 50 TO 10,000 HZ. (+25% OVER NOMINAL THORAD/AGENA PROFILE), 3 MINUTE DURATION
- SYNTHESIZED SHOCK - 11G MAX, 15 TO 450 HZ PER THORAD/AGENA PROFILE
- RESONANCE SEARCH - 1/4G, 14 TO 50 HZ CONDUCTED PRIOR TO AND AFTER SCHEDULED TEST
- OPERATIONAL VERIFICATION BETWEEN EACH TEST
- SYSTEM FUNCTIONAL VERIFICATION AT COMPLETION OF TESTS
- SYSTEM DISASSEMBLY FOR INSPECTION

ASCENT QUALIFICATION TEST
CR-8

TEST RESULTS

- UTB MODIFICATIONS ARE QUALIFIED FOR LAUNCH
 - DRUMS ROTATED IN BOTH DIRECTIONS BUT NO SLACK LOOPS DEVELOPED
 - POST TEST OPERATIONS CONFIRMED ACCEPTABLE FILM PATH MAINTAINED

- ANOMALIES DID OCCUR WHICH COULD CAUSE OPERATIONAL FAILURES

Handwritten signature and arrow pointing to the first bullet point.



ASCENT QUALIFICATION TEST
CR-8

ANOMALY

- o ROTARY SWITCH MOUNTING NUTS ON SWITCH PROGRAMMER
BACK OFF

CAUSE

- o INSUFFICIENT LOCKING

CORRECTIVE ACTION

- o INSTALLED SECOND JAM NUT WITH LOC-TITE ON THREADS

ANOMALY

- o T3 TIMER IN SWITCH PROGRAMMER TIMED OUT LATE

CAUSE

- o WIPER WIRE ON S-3 ROTARY SWITCH BROKEN WHEN MOUNTING
NUT BACK OFF

CORRECTIVE ACTION

- o SAME AS ABOVE



ASCENT QUALIFICATION TEST
CR-8

ANOMALY

- ROLLER GUIDE IN CHUTE ASSEMBLY BROKE

CAUSE

- MACHINED ROD PRODUCED NOTCH SENSITIVE GUIDE

CORRECTIVE ACTION

- GUIDE REDESIGNED TO GIVE ADDED STRENGTH
- NEW GUIDE QUALIFIED BY OVERDESIGN

ANOMALY

- ROTARY SWITCH GROUND ADJUST KNOB FELL OFF ON SWITCH PROGRAMMER

CAUSE

- SET SCREW BACKED OUT

CORRECTIVE ACTION

- INSTALLED SET SCREW WITH LOC-TITE ON THREADS

ASCENT QUALIFICATION TEST
CR-8

ANOMALY

- A.O. BOOT CLAMP CAME LOOSE

CAUSE

- CLAMP SCREWS BACKED OUT

CORRECTIVE ACTION

- SAFETY WIRE CLAMP SCREWS

ANOMALY

- BARREL/CONIC INTERFACE BOLT TORQUE INCREASED

CAUSE

- RE-USED GROUND TEST STEEL BOLTS

CORRECTIVE ACTION

- TITANIUM SCREWS ARE INSTALLED AT FINAL SYSTEM ASSEMBLY (ONE TIME USE)



ASCENT QUALIFICATION TEST
CR-8

ANOMALY

- THERMO SHIELD FASTENERS POPPED OUT OF RETAINERS

CAUSE

- IMPROPER INSTALLATION & POSSIBLE RE-USE OF FASTENERS

CORRECTIVE ACTION

- SELECTIVE INSTALLATION AND 100% INSPECTION TO VERIFY PROPER INSERTION
- INSTRUMENT SHIELDING REDESIGNED FOR IMPROVED INSTALLATION
- RESTRICT USE OF FASTENERS TO ONE-TIME ONLY

ANOMALY

- LOOSE DEBRIS IN SYSTEM

CAUSE

- DUST, METAL SHAVINGS, STRING NOT REMOVED BY PRE-TEST CLEANING

CORRECTIVE ACTION

- REDUCE MODIFICATION WORK AFTER SYSTEM VIBRATION
- RE-STRESS CLEANING PROCEDURES IN SYSTEM ASSEMBLY



ASCENT QUALIFICATION TEST
CR-8

ANOMALY

- o OSFG PROGRAMMER INOPERATIVE

CAUSE

- o TERMINALS BROKEN ON TRANSFORMER MODULE

CORRECTIVE ACTION

- o POT TERMINALS WITH RTV

ANOMALY

- o ECCENTRICITY FUNCTION OUTPUT HAS DISCONTINUITY IN OUTPUT SIGNAL

CAUSE

- o POTENTIOMETER WIPER LOSES CONTACT AT ONE SPOT IN CYCLE DUE TO INSUFFICIENT WIPER PRESSURE

CORRECTIVE ACTION

- o ALL POTENTIOMETERS TO BE REFURBISHED
 - o INCREASE WIPER PRESSURE
 - o INCREASE WIPER CONTACTS FROM 2 TO 3



ASCENT QUALIFICATION TEST
CR-8

ANOMALY

- o CABLE CONNECTOR CAME LOOSE CAUSING LOSS OF T/M MONITORS

CAUSE

- o IMPROPER INSTALLATION

CORRECTIVE ACTION

- o ADD ITEM IN FINAL ASSEMBLY PROCEDURE TO VERIFY EACH CONNECTOR IS FULLY ENGAGED IN DETENT



ASCENT QUALIFICATION TEST
CR-8

ANOMALY

- o SCREW BECAME LOOSE IN #2 SCAN HEAD ASSEMBLY

CAUSE

- o SCREW REMOVED FOR SPECIAL TEST - IMPROPER
INSTALLATION AFTER TEST

CORRECTIVE ACTION

- o ALL INSTALLATIONS TO BE MADE PER FLIGHT STANDARDS WITH
SCREWS GLYPED IN PLACE

ANOMALY

- o SHIM WASHER FOUND INSIDE #2 DRUM

CAUSE

- o SHUTTLE ASSEMBLY SHIM LODGED IN DRUM DURING
MANUFACTURING ASSEMBLY

CORRECTIVE ACTION

- o VERIFICATION MADE THAT SHIM DID NOT COME FROM CR-3
SHUTTLE ASSEMBLY

ASCENT QUALIFICATION TEST
CR-8

ANOMALY

- DRUM ROLLER SEPARATED FROM SUPPORT BLOCKS

CAUSE

- POOR EPOXY BOND ON INSTALLATION

CORRECTIVE ACTION

- INSPECT ALL ROLLERS UNDER MAGNIFICATION TO VERIFY EPOXY BOND

ANOMALY

- SLIT WIDTH MECHANISM BINDING ON INSTR #1 AS INDICATED BY T/M MONITOR

CAUSE

- NOT DETERMINED BY INSPECTION

CORRECTIVE ACTION

- TO BE INVESTIGATED IN BOSTON TEST LAB

READINESS REVIEW
CR-9

SPECIAL TEST PLAN - PRE-FLIGHT

- INCORPORATE CORRECTIVE ACTIONS RESULTING FROM THE ASCENT QUAL TEST *Time permitting*
- THOROUGHLY CLEAN
- ASSEMBLE SYSTEM IN ENVIRONMENTAL TEST CONFIGURATION
- CONDUCT ACCEPTANCE LEVEL VIBRATION TEST
 - INPUTS
 - 1G, 14 TO 20 HZ
 - 1/4G, 20 TO 50 HZ *As level*
 - 1G, 50 TO 2000 HZ
 - DURATION - APPROX. 3.5 MINUTES
 - LIMITING - INSTR. SUBSYSTEM 6G
- DISIC SUBSYSTEM 3G
- CONDUCT SYSTEM FUNCTIONAL VERIFICATION
 - 3 REV'S ORBITAL SIMULATION WITH A TO B TRANSFER
- DISASSEMBLE SYSTEM FOR INSPECTION
- BEGIN FLIGHT PREPS

READINESS REVIEW
CR-9

- CONFIGURATION DIFFERENCES
 - FROM CR-6
 - PULSATING PRESSURE MAKE-UP SYSTEM 3
 - PAN INSTRUMENT SUPPLY CASSETTES HAVE SERVO TENSION CONTROL
 - INTERMEDIATE ROLLER ASSY HAS TENSION BOBBLER
 - FROM CR-7
 - S/C TENSION SERVO
 - I/R BOBBLER
 - ASCENT CONFIGURATION
 - FROM CR-8
 - STB MATERIAL UTILIZED
 - FROM CR-6, CR-7, CR-8
 - SPLIT LOAD ON #1 INSTRUMENT (800' SO242/3404)
 - PMU LOW LEVEL DISABLED

READINESS REVIEW
CR-9

- SPECIAL SYSTEM VIBRATION TEST
 - RTV APPLICATION STICK FOUND-STICK IS NORMALLY USED IN MANUFACTURING SHOP
 - NO OPERATIONAL FAILURES ATTRIBUTED TO VIBRATION TEST
- SYSTEM VERIFICATION TEST ANOMALIES
 - DELAY TIMER IN SLOPE PROGRAMMER TIMED OUT EARLY (SINGLE CHANNEL HAYDON TIMER)
 - SWITCH PROGRAMMER TIMER #1 TIMED OUT BUT FAILED TO START TIMER #2 AND #3 (FOUR CHANNEL HAYDON TIMER)
 - CAUSE OF BOTH ANOMALIES ATTRIBUTED TO NOISE SENSITIVITY AND SUSCEPTABILITY OF HAYDON TIMER
 - CORRECTIVE ACTIONS - REPLACE HAYDON TIMERS, CONDUCT SUBSYSTEM THERMAL ALTITUDE TESTS, VERIFY SYSTEM PERFORMANCE
 - ADDITIONAL ENGINEERING ANALYSIS IN PROCESS
 - ALTERNATE TIMER PROCUREMENT
 - IMPOSE SYSTEM EMC TESTS
 - CONSTANT TENSION ASSEMBLY - S/C TENSION SERVO
 - ERRATIC LINEAR MOTION OBSERVED DURING DYNAMIC OPERATIONS
 - CAUSE - SIDE LOADING BY NEGATOR SPRING
 - CORRECTIVE ACTION - STRAIGHTEN END OF NEGATOR SPRING TO REDUCE LOADING FROM CURL

READINESS REVIEW
CR-9PRE-FLIGHT SCHEDULE

- INSPECTION AND MODIFICATIONS COMPLETE - OCT 16
- SYSTEM VIBRATION - OCT 17
- POST VIBRATION SYSTEM VERIFICATION - OCT 18
- INSTRUMENT CLEANING - OCT 24
- PYRO INSTALLATION - NOV 4
- SRV PRE-FLIGHT ASSEMBLY - NOV 12
- INSTRUMENT READINESS TEST - NOV 12 16
- SYSTEM ASSEMBLY & FLIGHT LOAD - NOV 17
- FINAL OPERATIONAL VERIFICATION - NOV 19
- RECEIVING CHECKOUT AT VAFB - NOV 20
- AGENA MATE AND CONFIDENCE TEST - NOV 21
- LAUNCH CHECKOUT - NOV 26

READINESS REVIEW
CR-9 [REDACTED]

○ CHANGES TO [REDACTED] FOR MISSION 1108

- ALL MAJOR PROGRAMS MODIFIED TO ACCEPT ASCENDING/
DESCENDING MODE OF OPERATION
- DAILY SUMMARY REPORTING PROCEDURES CHANGES TO
BETTER HANDLE CASE WHEN ONE CAMERA FAILS
- DAILY SUMMARY REPORTS CHANGED AS DESIRED BY SOC

○ TESTS OF [REDACTED] FOR MISSION 1108

- CPX INVOLVING ONLY HQ. COMM CENTER AND HQ.
COMPUTERS RUN 1 NOV. '69
- RESULT OF CPX: [REDACTED] READY FOR MISSION 1103