Closure Memorandum				
Case Number:	13-0054-I	Date of Entry:	14 May 2015	
Primary Investigator:				
	Alleg	gation Information		
(OIG) received an provided defective lectrical malfund NRO OIG initiated	allegation that re parts and/or service of a	, a technician emplo quality less than agreed ne Aerospace Data Facilit alleged actions by	RO) Office of Inspector General by Eaton Corporation, to by the NRO that caused an cy – Southwest (ADF-SW). The potentially violated 18 laims.	
Last Investigative	*			
	Case (Closure Justification		
system was active heads. The autom (SOC) did not occ delayed notificati department only	an electrical failure that cau ated within The heat a nated emergency notification	and smoke activated smo on from to the 24 h vas disconnected (see be e department. Security co d signs of fire in Th	in at the ADF- the fire, the fire suppression oke detectors and sprinkler our Security Operations Center elow discussion). This caused a ontacted the NASA fire here were no injuries or loss of	
maintained by Ea complete forensics report to the inductor at causing capacitor	failed to proper ter he completed the servi s to fail resulting in an oil s	nctor on the CFOAM cont to replace a recalled part rly reconnect the positive ice on Energy bu spill which caused the inst ere was no evidence to s	According to the Eaton fire e lead from the DC filter assembly tilt up within the filter assembly	

Page 1

Approved for Release: 2021/04/20 C05132432

-SECRET//TALENT KEYHOLE//REL TO USA, FVEY

	(b)(3) (b)(1)
KI/TK//REL) Boeing completed recovery activities under the NRO000-09-C-0384 (CFOAM) contract. Repaired or replaced Motor Control Center, chillers, condensers, water pumps, transformers, and bypass switches. The total cost also included the rental of a 750-1,000 kilowatt transportable generator from Hobbs, New Mexico for	(0)(1)
and a transportable 500 ton air-cooled chiller from Dallas, Texas for and maintain the rented equipment until repairs were completed was Eaton replaced	(b)(3) (b)(4)
(U//FOUO) In addition to investigating potential violation of 18 U. S. C. § 287, the OIG reviewed Boeing's involvement regarding the fire alarm outage. As the prime for the CFOAM contract, Boeing is responsible for testing and maintaining the fire alarm system at ADF-SW. On 15 August 2012, a subcontractor working on a security system upgrade project disconnected the fire alarm connectivity from to the 24 hour SOC. The subcontractor reported the disconnection to Boeing. Although the issue was discussed amongst Boeing management, Boeing failed to notify government personnel that the alarm had been disconnected and never took action to correct the situation. Boeing reconnected the fire alarm nine months later and after the fire event. The failure on Boeing's part to reconnect the alarm resulted in additional burn time before the fire department was called. (see IARs and Fire Incident Review)	(b)(3)
(U/ FOUO) The OIG concluded that since the fire was caused by mistake during service	(6)(3)
and there is no evidence to suggest that he intended to cause harm to the Government; there is no evidence that violated 18 U.S.C. § 287. According to Boeing legal counsel Boeing insurance does not cover loss related to the fire based on the premise that the government is self-insured and therefore Boeing could not be held directly accountable. The NRO raised this question to NRO OGC, but was unsuccessful in resolving the issue.	(b)(3 ₎
(U//FOUO) The final cost of the ADF-SW fire recovery effort was Boeing's fee was or approximately The OIG briefed the CFOAM Contracting Officer on the facts of the case including the delayed fire response due to Boeing's failure to properly manage the fire safety system. As a result of the facts developed by the OIG, the the CO reviewed Boeing's prior earned award fee and reduced the subsequent award fee by the or Boeing previously received. No additional OIG actions required.	(b)(3) (b)(4)
(U/ /FOUO) On 17 June 2013, shortly after the fire at ADF-SW, there was an electrical incident in the at ADF-C, causing activation of sprinklers and fire alarms. OIG looked into the matter to determine if the two instances were related and if not, were there potential	(b)(3)
violations. OIG found that an outdated drawing was being used which caused the incorrect wiring (see email in docs tab). There appears to be no connection between the two incidences and no potential violations. Therefore, OIG took no additional action on this matter.	(b)(3)