

~~TOP SECRET~~

TALENT KEYHOLE

HANDLE VIA

BYEMAN
CONTROL SYSTEM~~(S)~~ NATIONAL RECONNAISSANCE OFFICE

WASHINGTON, D.C.

THE NRO STAFF

FILE

PRO ~~ALF~~

A6 e(4)b

MEMORANDUM FOR MR. PLUMMER

SUBJECT: Itek's Analysis of the Metric Pan

A copy of Itek's briefing to Dr. Cook and Dr. Hall which raised questions about the utility and feasibility of the Metric Pan System (MPS) is at TAB A. Itek had two main points:

A. An MPS with a 5 arc second attitude error would not be useful, and

B. The ability to hold the error to 5 seconds is doubtful.

We had DMA double check the vertical positional error claimed by Itek due to the 5 second attitude error, and they determined that Itek must have been assuming a scan angle of 60°. As DMA's 25 February 1975 input to us shows (TAB B), a 5 second MPS will not meet the requirement outside 45° scan. DMA has considered this in their collection analysis, as we take little imagery outside 45°.

Lt Colonel Hutchison, Colonel Anderson (SP's HEXAGON Program Manager), and Dr. Howard of Aerospace reviewed the Perkin-Elmer error budget and supporting analyses and test results at the Danbury plant on 16 October 1975. As the result of that review, it was concluded that the largest concern of Itek's, 20 microns of non-linear smear, was invalid. It was also concluded, however, that Perkin-Elmer's 4.9 second error budget might be optimistic, more suitable for a goal than a hard specification. A summary of Perkin-Elmer's analysis is at TAB C.

At this point DMA stated that their analysis (TAB B) shows that 5 seconds is acceptable as a goal, if 10 seconds is set as the limit. Based on this 5 to 10 second requirement set by DMA, SAFSP concluded that the MPS was a low risk program.

HEXAGON

HANDLE VIA

BYEMAN

CONTROL SYSTEM

CLASSIFIED BY: BYEMAN - 1 EXEMPT FROM
GENERAL DECLASSIFICATION SCHEDULE OF
EXECUTIVE ORDER 11652 EXEMPTION CATE-
GORY 562 DECLASSIFY ON IMP DET.~~TOP SECRET~~

CONTROL NO. Internal

COPY 1 OF 2 COPIES

PAGE 1 OF 2 PAGES

It is our understanding that Itek has presented their analysis to ASD(I) and generated enough concern for Dr. Hall to delay sending a Mapping Camera System/MPS decision memorandum until after he has consulted with you.

In summary, we have shown the Itek Analysis to be invalid, and it is recommended that it be so reflected in your discussion with Dr. Hall. There is no technical reason that this decision memorandum should be further delayed.

HAROLD P. WHEELER, JR.
Colonel, USAF
Director

Attachments

HANDLE VIA
BYEMAN /TALENT-KEYHOLE
CONTROL SYSTEM

~~TOP SECRET~~
CLASSIFIED BY BYEMAN 1 EXEMPT FROM
GENERAL DECLASSIFICATION SCHEDULE OF
EXECUTIVE ORDER 11652 EXEMPTION CODE
GORY 5B2 DECLASSIFY ON: IMP DET

CONTROL NO Internal
COPY 1 OF 2 COPIES
PAGE 2 OF 2 PAGES

ABSOLUTE POSITIONING
(METERS, (17))

REQUIREMENTS

CAPABILITY

1965 USIB	6/75 J SOP		75/55 EXPECTED FUTURE REQMT (1,4)
	Current FIRM	TECHNICAL OBJECTIVE	
64	29 64 62	36 12	29 10.7
64	29 64 62	36 12	29 10.7
55	17 46 29	32 14	18 10.6

CURRENT FRAME(1)	FRAME WITH GEOPACK	3 SEC PAN WITH GEOPACK	5 SEC PAN WITH GEOPACK
✓ 19	135	13	10
19		13	11
✓ 14	15	12	13

∇_x
 ∇_y
 ∇_z

- NOTES (1) SOURCE: DMA
(2) ABSOLUTE ATTITUDE DETERMINATION
(3) GEOPACK OPERATIONAL ON SV-13 (1977)
(4) COVERAGE 3000 HARD TARGETS IN DENIED AREAS

DMA
SAYS
~10.4

TAB A

RELATIVE POSITIONING
(METERS, 1 ∇)

REQUIREMENTS

1:50,000 CLASS A MAP	PAVE STRIKE	1:250,000 CLASS A MAP
12	13	59
12	13	59
3	9	15
10-20 N. MI	300 N. MI.	20 N. MI.
SELECTED		WORLD WIDE

NOTES

- 1) PRODUCTION ACTUALS
- 2) BEST-CASE ESTIMATE INCLUDING ATTITUDE
ERROR AND 10 μ M MENSURATION ERROR
ONLY; ONLY 2 MODELS

CAPABILITY

CURRENT FRAME	2 SEC PAN	5 SEC PAN
8	2	4
8	4 - 7	8 - 14
6 ⁽¹⁾	8 ⁽²⁾	15 ⁽²⁾

∇_x

∇_y

∇_z

IST.

OVERAGE
REQUIRED

SOURCES OF UNCERTAINTY IN PAN CALIBRATION

- STUDY 10176 (1974) - ADVANCED PAN CAMERA BREADBOARD TEST
+ 20 MICRONS DYNAMIC FILM STRETCH
- STUDY 10092 (1975) - PAN CALIBRATION VERIFICATION (SV 7)
UNEXPLAINED INCONSISTENCY BETWEEN SCAN
ANGLE AND TIMING MARK POSITIONS

1.6 μ \rightarrow 1 sec

SOURCES OF PAN ERROR

	<u>SEC</u>
DYNAMICS BETWEEN SCAN ANGLE MARKS	<u>2.5</u>
✓ .001 INCH BEARING RUNOUT .0002 μ per	2.0 \Rightarrow 1.5
13 BIT ENCODER (1% CALIBRATION ACCURACY)	1.0
STELLAR TO PAN BORESIGHT (KNEE)	2.0 \Rightarrow 2.2
CALIBRATION	
STELLAR TO PAN BORESIGHT STABILITY	1.0
ATTITUDE SENSOR INTERNAL STABILITY	<u>1.0</u> \Rightarrow 1.5
SCAN RATE UNCERTAINTY	1.8
PLATEN-LENS LOCK UNCERTAINTY	<u>2.0</u> < 1
R SS TOTAL	4.9

CONCLUSION: 5 SEC REQUIRES UNREALISTIC ERROR BUDGET

REASONS FOR MORE FRAME CAMERAS

- UNCERTAINTY IF PAN CAN BE CALIBRATED TO REQUIRED ACCURACY
- IMPROVED ABSOLUTE POSITIONING WITH GEOPACK STARTING IN 1977
- ECONOMY IN MAP PRODUCTION
- RELIABILITY - LOSS OF SINGLE PAN MEANS NO MAPPING
 - LOSS OF SINGLE STELLAR HAS 3X IMPACT ON PAN COMPARED TO FRAME
- DEDICATED COVERAGE FOR MAPPING REQUIREMENTS