

MEMORANDUM FOR: Director of Special Projects

SUBJECT


: Photo Reconnaissance Systems Report No. 67

## 1. CORONA

#### A. Accomplishments

- 1. QR-2 (Mission Ill2) was successfully launched at 1325 hours PST. Operation is normal with AP working personnel and WCPO Duty Officers using the new quarters in the STC. With the exception of the location of perigee, the mission was launched into the planned orbit. Perigee location was intended to be 35 degrees north descending; however, it was rotated to about 7 degrees south descending. The achieved perigee location will be rotated northward on the first DMU firing, and this should correct the problem. The rotation's only impact on the mission will be in higher photography in the prime area until the DMU is fired to rotate the perigee.
- 2. The switch programmer problem previously discussed was solved when failure analysis indicated a bad switch in the box that was replaced on QR-2. A wire bundle above the switch was riding on the switch when the cover of the box was closed. This was the only box with this type wire bundle routing. The switch was removed, and the wire bundle rerouted, thus solving the problem.
  - 3. CR-8's SRV's were accepted at GE on 12 November.





HANDLE VIA BYEMAN CONTROL SYSTEM ONLY



4. The special CORONA target acquisition software is in final checkout for an initial operating version. This version as well as the minimal documentation should be complete by 31 November.

## B. Problems

The CR-15 slope programmer is continuing failure analysis in regard to problem discussed in past reports.

### C. Projected Status

- 1. CR-13. Pre-flight preps.
- 2. CR-14. Back-up thermal taping.
- 3. CR-15. Block test.
- 4. CR-16. Tracking.
- 5. CR-8. Instrument mods.

#### II. HEXAGON

#### A. General

1. The Project Office and TRW personnel reviewed the following spares data packages on 17 and 18 November:


1A4 (Digital Data Acquisition System)


3Al-B (Output-Film Drive Capstan Electronics)

6Al (Supply Brushless Motor Electronics)

6A2 (Supply Servo Electronics)

BYE-108972-70 Page Two





On 19 November, TRW reviewed:

1A2 (Modulation Computer)


5Al (Articulated Steerer Servo)


5A2 (Edge Sensor Electronics)

All packages were satisfactory but were not tech certified by the Project Office because the appropriate contractor personnel had not signed the tech cert documents. After execution of the tech cert, the spares will be bought off via DD-250 and the spares sent to the west coast. Latest schedule indicates the last spare AVE electronic package arriving at PE in January.

- 2. The core for the "Watermelon IV" film roll (for supply caging deletion study) was sent to Kodak this week for spooling. The plan is to get the film roll back at PE by I December to support the x- and y-axis vibration tests scheduled for December. January 8 is the target date for decision on the caging deletion. EK delivered two "Pumpkin" (110 K feet) rolls, three "Cucumber" (26 K feet) rolls (one is color) and a supply of Versamat B chemistry to PE this week.
- 3. TRW and PE reliability are working together to have TRW recommend a non-destructive test program for potentiometers which is more stringent than the current potentiometer acceptance test program. In the past, several pots have passed acceptance tests but failed later in system level tests. It is hoped TRW can recommend a test program which will keep this from occurring in the future.
- 4. The CEI specification for the Forward Assembly Kit has been reviewed and found to contain reference to an

BYE-108972-70 Page Three






incorrect part number for the steerer motor. Additionally, there was no reference to a requirement for a "roller run down" test. PE has been advised to correct the deficiencies in a revised spec and to resubmit for approval.

- 5. Longitudinal color qual tests at the 5th color frequency (blue) on the Optical Bar were conducted and found to be out of spec. Results of other color tests on the bar indicate that the bar should be within spec. PE believes there may have been a problem with the test equipment and is analyzing the tests and the equipment to understand the problem.
- 6. Qualification certification meetings for eleven electronic packages are scheduled for the week of 7 December.
- 7. At the Operations Interface Working Group on 12 November, the SPO stated his agreement to share telemetry tapes with PE when they arrive at LMSC and is in the process of arranging the details with LMSC. A subgroup to the Software CCB is being formed to assume the responsibility for recommending which software models will be used for support of a given flight or rehearsal. The SSPO representative recommended that the orbit for the November rehearsal be such that the maximum Vx/h be 0.035 and the scan be limited to  $\frac{1}{2}$  30 degrees. generated a 125 X 139 NM orbit which met these constraints. The rehearsal went very well, with very complimentary comments from the Technical Adviser with regard to the PE areas of responsibility.

The post-milestone 8 configuration management plan for the flight software is ready for distribution. LMSC is going to provide a tape from the thermal/vacuum tests to the STC for mode validation and rehearsal activities. The establishment of the PCM format subgroup to the Operations IWG and TT&C IFWG was announced. The software with the SS-required modifications will be available for the December

BYE-108972-70 Page Four

Comment of the second



rehearsal. One flight-limiting software problem remains in the RTS software, which precludes processing the high-sample-rate SS data from the disk on the average of about one out of two attempts. Tests are being run to isolate the problem so that corrective action can be taken.


8. In the afternoon of 12 November, a meeting with SSPO, SPO and Aerospace was held to discuss the PE interface with Aerospace in the TA staff. The coordination role of Aerospace was determined to be in command message checking, specifications of station pass requirements, providing FRT and attitude data, mission profile planning and telemetry mode scheduling, and post-flight critique participation.

On 17 November LMSC presented their plans and procedures for support of the TA staff. The general presentation in the morning showed good thought and was very interesting. LMSC now has a couple of analysts who have worked at the STC in the vehicle analysis group for CORONA who have greatly influenced the mode of operation of LMSC in the TA staff. Arrangements are being made for PE to hear the general presentation. The detailed presentation in the afternoon was not nearly as well thought out and shows LMSC has a lot of detailed planning to do.


In the afternoon of 18 November, an informal discussion between SSPO and SPO resulted in a statement of agreement, satisfactory to both, on the only item discussed in the TA staff relationship meeting which did not conclude with a summary statement of agreement. This item related to contractor support of SCF rehearsal planning. SSPO also reviewed the position statements and summary remarks prior to their being presented at the 19 November Managers Meeting.


BYE-108972-70 Page Five

C/m/cmi



- With regard to MACFACT and HOPE, the following agreements were reached in discussions between WCPO, TRW, and PE/WCFO:
  - A. PE/WCFO will be responsible for modification/maintenance of MACFACT software with all modifications approved by WCPO. TRW will continue to support MACFACT as required for development of HOPE software.
  - B. WCPO will provide all software necessary for interface between the MPR (Mission Performance Report) and HOPE. This will be a minimum software effort involving extraction of clock correlation, rev-op correlation, and orbit parameters from the MPR.
- 10. Messrs. Weiss and from ESL visited the West Coast Computer Facility to discuss their processing requirements and to be briefed on the hardware/software configuration of the Computer Facility.
- 11. The Headquarters Calcomp routines were modified to insure the calling sequences in scale, axis and plots to be compatible with the West Coast 760 Calcomp software.
- visited LMSC on 17-19 November to prepare a Block II briefing for presentation at the HEXAGON Managers Meeting. Of the four configurations studied during the past two weeks—with and without added film capability and with and without added orbit adjust propellants—one hardware configuration was selected for additional study prior to asking the NRO in January for funding. The P-13 concept would include:





- A. No additional film capacity.
- B. 'Super' looper, simplified film transport, brush motors/tachometers, and improved emergency shut down.
  - C. 150 percent OA propellant.
- D. 90-day (84 X 144 NM) to 120-day (88 X 140 NM) missions.
- E. Some additional redundancies/simplification to try to achieve a .75 system reliability.

The associated sensor subsystem ROM costs are as follows:

- A. Non-recurring \$35.3M
- B. Recurring:
  - (1) 4/year \$60.4M per year
  - (2) 3/year 49.6M per year


The PE proposal for units 6-12 contained equivalent 4 per year costs of \$62.0M per year.


#### B. Model Status

## 1. Development Model (SDV-III)

On 18 November, SDV-III completed day 18 of the thermal vacuum qualification test successfully with rewinds of up to 69 inches/sec being demonstrated. Following day 18,

> BYE-108972-70 Page Seven





RV-3 had been loaded to greater than 26,000 feet and transfer from RV-3 to RV-4 was accomplished. Day 19 (the last day of sensor operation) was completed on 19 November, including rewinds of up to 81 inches/sec (the maximum) and as much as 40 minutes per day of camera operation. SDV-III has now transferred approximately 60,000 feet of film per camera during this test, and performance has been excellent. Quick look data indicates that relative humidity problems may be less severe than anticipated.

# 2. SV-1 (SN-003)


### (A) Midsection

R&I testing has not yet resumed due to difficulties with the looper modification installation and checkout. A problem was encountered late Wednesday evening when the "A" camera "ran away" during a mono creep operation. Attempts to remove approximately 40 feet of loose material from the supply, which resulted from the uncontrolled shut down, showed a foldover in the FEV (Film Exit vestibule). The supply was subsequently removed, resulting in an additional four-day slip.

#### (B) Forward Section

Articulator steerer SN-5002 has been replaced with the unit previously scheduled for installation in the SV-2 forward section. This replacement was required because a quad ring seal was inadvertently left out of the steerer at the time of manufacture and assembly. Forward section checkout activities resumed with tracking/stacking tests performed on TUA SN-015 (Bay No. 1) on 19 November 1970.

BYE-108972-70
Page Eight



# (C) Aft Section

LMSC problems continue, but the aft section is not on the critical path.

# 3. SV-2 (SN-002)


SN-002 is experiencing two prime performance anomalies as previously reported:


- (A) Metering capstan oscillation at discreet velocities.
- (B) Near-saturation of the "A" and "B" supply steerer. Present contractor plans, agreed to by the government, include the incorporation of the looper modification kit and a review before proceeding with the MFN 3.09 test sequence. The Project Office and the contractor have agreed that all efforts will be made to resolve the two prime problems.

### 4. SV-3 (SN-004)

"B" side platen tests will be complete on 20 November. The remaining subassembly installation and testing for Optical Bar "B" will be complete on 24 November, with clean room testing scheduled for 25 November completion. Two camera assembly vibration testing is scheduled for 3 December, but if PE encounters no problems, they can probably start this test a day or two early. Other schedule milestones remain the same as reported last week.

BYE-108972-70 Page Nine





# (C) Aft Section

LMSC problems continue, but the aft section is not on the critical path.

# 3. SV-2 (SN-002)

SN-002 is experiencing two prime performance anomalies as previously reported:


- (A) Metering capstan oscillation at discreet velocities.
- (B) Near-saturation of the "A" and "B" supply steerer.

Present contractor plans include the incorporation of the looper modification kit and then proceeding with the MFN 3.09 test sequence. The Project Office is reviewing the contractor plans.

## 4. SV-3 (SN-004)

"B" side platen tests will be complete on 20 November. The remaining subassembly installation and testing for Optical Bar "B" will be complete on 24 November, with clean room testing scheduled for 25 November completion. Two camera assembly vibration testing is scheduled for 3 December, but if PE encounters no problems, they can probably start this test a day or two early. Other schedule milestones remain the same as reported last week.

BYE-108972-70 Page Nine





III. Meetings Requiring Participation of Headquarters Personnel

Date

Subject

Attendees

PE

Follow-on Cost Audit

Personnel

Messrs.

will be

on annual leave Z7 November.

PMO/PRS/OSP

#### Distribution:

Cy 1 - D/OSP

Cy 2 - ADD/OSP

Cy 3 - D/PRS/OSP

Cy 4 - EO/OSP

Cy 5 - CS/OSP

Cy 6 - C/PAD/OSP

Cy 7 - C/SB/OSP

Cy 8 - C/SS/OSP

Cy 9 - RB/OSP

Cy 10 - PRS/File

Cy 11 - PRS/Chrono

Cy 12 - NEPO

Cy 13 - WCPO

BYE-108972-70 Page Ten



051	35547 Approved for Release: 2018/11/08 C05135547						
n e	FORM 2820	CLASSIFIED MESSAGE					
边	SECRET				E MINITUM C		
2	FILE INFO (When Filled In)						
	REPRODUCTION PROHIBITED 24 NOV70 05 102					and the second second	
	ACTION 1		6	12	16	· · · · · · · · · · · · · · · · · · ·	
	3 4		8 9	13 14	18	1	
wmn a	> 5		10	15	20		
0000	IN 95697						
	TOPPECAT	T 2461412 NO	V 70 CITE	4761.			
10	IMMEDIATE WARDO INFO PRIORITY CHARGE, PLUM, PILOT						
1 3	HEAGIA-X	ي يې رسه					
€,3	( III 2 - I)			a in the same of t		<u> </u>	
, T	B. TELEMETRY DATA INDICATES A DISCREPENCY BETWEEN THE "CYCLE						
	MONITOR FOR THE FORWARD LOOKING CAMERA, FOLLOWING THE REV 79  OPERATE THE CO MONITOR SHOWED 2475 FRANCES ON THE TAKE-UP WHILE THE  FFP INDICATED THAT ACTUAL TAKE-UP DIAMETER WAS 18.63 INCHES						
a second	(IDMINALLY 270% FRANCS), A DIFFERENCE OF 225 FRANCS.						
·	C. AT THIS TIPE THERE IS NO EXPLANATION FOR THIS DISCREPANCY.						
1000	POSSIBLE CAUSES ARE INCORRECT TELEMETRY, LOOSE FILM WRAP ON THE						
2	TAKE-UP, MON-UNIFORM (LUMPY) FILM WRAP, OR ERROR IN THE FFP.						
	EVALUATION WILL CONTINUE WITH A POSSIBLE SCRUTION WHEN THE BUCKETY						
~ <u>~</u>	TILN 13 EXAMINED FOLLOWING RECOVERY.  U. THE FFR CONTROLS TAKE-UP CAPACILITY AND THE MAXIMUM TAKE-UP						
- <del>"</del>							
	DIAMETER ALLOWABLE IS 19.75 INCHES (APPROXIMATELY 3125 FRAMES).						
BHRH	AROVE THIS DIAMETER THERE IS A POTENTIAL TO JAM THE SYSTEM CAUSING						
	S CAMERA SYSTEM PAILURE. WE THEREFORE PLAN TO PUT A MAXIMUM OF 425						
	tone Frames (45 OF NEV SC) ON THE FORWARD-LOOKING CAMERA PRIOR						
	TO THE CUT-AND-WRAP OPERATION						
To garde St. Agricological Transfer of the state of the s	TO THE OUT MIN AL	eriya merginda takan da Mir	****	ena like like a el			
		a					
SAAA		***	* ************************************	ی در			
4444		4 1 3 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4	Markette State of the Control of the	ing the second of the second o	was in the same of		

(b)(1) (b)(3)

(b)(3)

(b)(1)