

Classification

~~SECRET~~



[REDACTED]

11106

[REDACTED]

CR-9

READINESS REVIEW

OCT 17, 1969

see why you
need to justify
things. I don't
like it there
"anomalous" on
CR-8

Declassified and Released by the NRO

In Accordance with E. O. 12958

on NOV 26 1997

~~SECRET~~

[REDACTED]

~~SECRET~~

READINESS REVIEW

CR-9

- CONFIGURATION DIFFERENCES FROM BASELINE (CR-6)
 - PULSATING PRESSURE MAKE-UP SYSTEM
 - PAN INSTRUMENT SUPPLY CASSETTES HAVE SERVO TENSION CONTROL
 - INTERMEDIATE ROLLER ASSY HAS TENSION BOBBLER
- CONFIGURATION DIFFERENCES FROM LAST -3 FLIGHT (CR-7)
 - S/C TENSION SERVO
 - I/R BOBBLER
 - ASCENT CONFIGURATION
- CONFIGURATION DIFFERENCES FROM ASCENT QUAL (CR-8)
 - STB MATERIAL UTILIZED IN CR-9

~~SECRET~~

~~SECRET~~

ASCENT QUALIFICATION TEST
CR-8

OBJECTIVE

- QUALIFY THE UTB MODIFICATIONS INCORPORATED IN THE
CR SUBSYSTEM (ASCENT MODE)
 - I/R BOBBLER
 - SUPPLY CASSETTE TENSION SERVO
 - SUPPLY CASSETTE BRAKE LOCKED - NO POWER DURING ASCENT

~~SECRET~~

~~SECRET~~

ASCENT QUALIFICATION TEST

CR-8

TEST PLAN

- SYSTEM IN FLIGHT CONFIGURATION EXCEPT DISC AND TAPE RECORDER
SUBSYSTEM NOT INSTALLED
- [REDACTED] SIMULATION - 3.5G, 14 TO 20 1/2 HZ, 35 SECOND DURATION
- ACOUSTIC SIMULATION - 156 DB, 50 TO 10,000 HZ. (+25% OVER NOMINAL
THORAD/AGENA PROFILE), 3 MINUTE DURATION
- SYNTHESIZED SHOCK - 11G MAX, 15 TO 450 HZ PER THORAD/AGENA PROFILE
- RESONANCE SEARCH - 1/4G, 14 TO 50 HZ CONDUCTED PRIOR TO AND AFTER
SCHEDULED TEST
- OPERATIONAL VERIFICATION BETWEEN EACH TEST
- SYSTEM FUNCTIONAL VERIFICATION AT COMPLETION OF TESTS
- SYSTEM DISASSEMBLY FOR INSPECTION

~~SECRET~~

~~SECRET~~

ASCENT QUALIFICATION TEST
CR-8

TEST RESULTS

- UTB MODIFICATIONS ARE QUALIFIED FOR LAUNCH
 - DRUMS ROTATED IN BOTH DIRECTIONS BUT NO SLACK
LOOPS DEVELOPED
 - POST TEST OPERATIONS CONFIRMED ACCEPTABLE
FILM PATH MAINTAINED
- ANOMALIES DID OCCUR WHICH COULD CAUSE OPERATIONAL FAILURES

~~SECRET~~

~~SECRET~~

ASCENT QUALIFICATION TEST

CR-8

ANOMALY

- ROTARY SWITCH MOUNTING NUTS ON SWITCH PROGRAMMER
BACK OFF

CAUSE

- INSUFFICIENT LOCKING

CORRECTIVE ACTION

- INSTALLED SECOND JAM NUT WITH LOC-TITE ON THREADS

ANOMALY

- T3 TIMER IN SWITCH PROGRAMMER TIMED OUT LATE

CAUSE

- WIPER WIRE ON S-3 ROTARY SWITCH BROKEN WHEN MOUNTING
NUT BACK OFF

CORRECTIVE ACTION

- SAME AS ABOVE

~~SECRET~~

~~SECRET~~

ASCENT QUALIFICATION TEST

CR-8

ANOMALY

- ROLLER GUIDE IN CHUTE ASSEMBLY BROKE

CAUSE

- MACHINED ROD PRODUCED NOTCH SENSITIVE GUIDE

CORRECTIVE ACTION

- GUIDE REDESIGNED TO GIVE ADDED STRENGTH
- NEW GUIDE QUALIFIED BY OVERDESIGN

ANOMALY

- ROTARY SWITCH GROUND ADJUST KNOB FELL OFF ON SWITCH PROGRAMMER

CAUSE

- SET SCREW BACKED OUT

CORRECTIVE ACTION

- INSTALLED SET SCREW WITH LOC-TITE ON THREADS

~~SECRET~~

~~SECRET~~

ASCENT QUALIFICATION TEST
CR-8

ANOMALY

- A.O. BOOT CLAMP CAME LOOSE

CAUSE

- CLAMP SCREWS BACKED OUT

CORRECTIVE ACTION

- SAFETY WIRE CLAMP SCREWS

ANOMALY

- BARREL/CONIC INTERFACE BOLT TORQUE INCREASED

CAUSE

- RE-USED GROUND TEST STEEL BOLTS

CORRECTIVE ACTION

- TITANIUM SCREWS ARE INSTALLED AT FINAL SYSTEM ASSEMBLY (ONE TIME USE)

~~SECRET~~

~~SECRET~~

ASCENT QUALIFICATION TEST

CR-8

ANOMALY

- THERMO SHIELD FASTENERS POPPED OUT OF RETAINERS

CAUSE

- IMPROPER INSTALLATION & POSSIBLE RE-USE OF FASTENERS

CORRECTIVE ACTION

- SELECTIVE INSTALLATION AND 100% INSPECTION TO VERIFY PROPER INSERTION
- INSTRUMENT SHIELDING REDESIGNED FOR IMPROVED INSTALLATION
- RESTRICT USE OF FASTENERS TO ONE-TIME ONLY

ANOMALY

- LOOSE DEBRIS IN SYSTEM

CAUSE

- DUST, METAL SHAVINGS, STRING NOT REMOVED BY PRE-TEST CLEANING

CORRECTIVE ACTION

- REDUCE MODIFICATION WORK AFTER SYSTEM VIBRATION
- RE-STRESS CLEANING PROCEDURES IN SYSTEM ASSEMBLY

~~SECRET~~

~~SECRET~~

ASCENT QUALIFICATION TEST
CR-8

ANOMALY

- o CABLE CONNECTOR CAME LOOSE CAUSING LOSS OF T/M MONITORS

CAUSE

- o IMPROPER INSTALLATION

CORRECTIVE ACTION

- o ADD ITEM IN FINAL ASSEMBLY PROCEDURE TO VERIFY EACH CONNECTOR IS FULLY ENGAGED IN DETENT

~~SECRET~~

~~SECRET~~

ASCENT QUALIFICATION TEST
CR-8

ANOMALY

- o OSFG PROGRAMMER INOPERATIVE

CAUSE

- o TERMINALS BROKEN ON TRANSFORMER MODULE

CORRECTIVE ACTION

- o POT TERMINALS WITH RTV

ANOMALY

- o ECCENTRICITY FUNCTION OUTPUT HAS DISCONTINUITY IN OUTPUT SIGNAL

CAUSE

- o POTENTIOMETER WIPER LOSES CONTACT AT ONE SPOT IN CYCLE

CORRECTIVE ACTION

- o TO BE INVESTIGATED BY VENDOR FAILURE ANALYSIS

~~SECRET~~

~~SECRET~~

ASCENT QUALIFICATION TEST

CR-8

ANOMALY

- SCREW BECAME LOOSE IN #2 SCAN HEAD ASSEMBLY

CAUSE

- SCREW REMOVED FOR SPECIAL TEST - IMPROPER INSTALLATION AFTER TEST

CORRECTIVE ACTION

- ALL INSTALLATIONS TO BE MADE PER FLIGHT STANDARDS WITH SCREWS GLYPED IN PLACE

ANOMALY

- SHIM WASHER FOUND INSIDE #2 DRUM

CAUSE

- SHUTTLE ASSEMBLY SHIM LODGED IN DRUM DURING MANUFACTURING ASSEMBLY

CORRECTIVE ACTION

- VERIFICATION MADE THAT SHIM DID NOT COME FROM CR-8 SHUTTLE ASSEMBLY

~~SECRET~~

~~SECRET~~

ASCENT QUALIFICATION TEST

CR-8

ANOMALY

- DRUM ROLLER SEPARATED FROM SUPPORT BLOCKS

CAUSE

- POOR EPOXY BOND ON INSTALLATION

CORRECTIVE ACTION

- INSPECT ALL ROLLERS UNDER MAGNIFICATION TO VERIFY EPOXY BOND

ANOMALY

- SLIT WIDTH MECHANISM BINDING ON INSTR #1 AS INDICATED BY T/M MONITOR

CAUSE

- NOT DETERMINED BY INSPECTION

CORRECTIVE ACTION

- TO BE INVESTIGATED IN BOSTON TEST LAB

~~SECRET~~

~~SECRET~~

READINESS REVIEW

CR-9

SPECIAL TEST PLAN - PRE-FLIGHT

- INCORPORATE CORRECTIVE ACTIONS RESULTING FROM THE ASCENT QUAL TEST
- THOROUGHLY CLEAN
- ASSEMBLE SYSTEM IN ENVIRONMENTAL TEST CONFIGURATION
- CONDUCT ACCEPTANCE LEVEL VIBRATION TEST
 - INPUTS
 - 1G, 14 TO 20 HZ
 - 1/4G, 20 TO 50 HZ
 - 1G, 50 TO 2000 HZ
 - DURATION - APPROX. 3.5 MINUTES
 - LIMITING - INSTR. SUBSYSTEM 6G
 - DISIC SUBSYSTEM 3G
- CONDUCT SYSTEM FUNCTIONAL VERIFICATION
 - 3 REV'S ORBITAL SIMULATION WITH A TO B TRANSFER
- DISASSEMBLE SYSTEM FOR INSPECTION
- BEGIN FLIGHT PREPS

~~SECRET~~

~~SECRET~~

READINESS REVIEW

CR-9

PRE-FLIGHT SCHEDULE

- O INSPECTION AND MODIFICATIONS COMPLETE - OCT 16
- O SYSTEM VIBRATION - OCT 17
- O POST VIBRATION SYSTEM VERIFICATION - OCT 18
- O INSTRUMENT CLEANING - OCT 24
- O PYRO INSTALLATION - NOV 4
- O SRV PRE-FLIGHT ASSEMBLY - NOV 12
- O INSTRUMENT READINESS TEST - NOV 12
- O SYSTEM ASSEMBLY & FLIGHT LOAD - NOV 17
- O FINAL OPERATIONAL VERIFICATION - NOV 19
- O RECEIVING CHECKOUT AT VAFB - NOV 20
- O AGENA MATE AND CONFIDENCE TEST - NOV 21
- O LAUNCH CHECKOUT - NOV 26

~~SECRET~~