

(DISC XVIII) INDICATED THAT CERTAIN COMPUTER WIRING MIGHT BE SUSCEPTABLE TO VIBRATION DAMAGE UNLESS THE METHOD OF TIEING DOWN THE WIRING WAS CHANGED. THE COMPUTER INSTALLATION IN 11/3 IS SIMILAR TO THE INSTALLATION IN VEHICLE 1/62 (DISC XVII). IT WAS THEREFORE CONSIDERED APPROPRIATE TO ACCOMPLISH THE SAME FIX IN 1/62. THE COMPUTER HAS BEEN REMOVED FROM 1/62. FOLLOWING THE RE-INSTALLATION OF THE COMPUTER, IT WILL BE NECESSARY TO REPEAT THE SYSTEM'S RUN ON THE LAUNCH PAD. THIS WILL CAUSE A ONE DAY SLIPPAGE IN THE LAUNCH. THE NEW LAUNCH DATE IS NOW 9 NOVEMBER.

