

**SECRET**  
(When Filled In)

1400081664

FILE INFO

REPRODUCTION PROHIBITED

10 SEP 68 07

ACTION	1	6	11	16
	2	7	12	17
	3	8	13	18
	4	9	14	19
	5	10	15	20

NNNN [REDACTED]

~~TOP SECRET~~ 301936Z SEP 68 CITE [REDACTED]

PRIORITY [REDACTED] INFO [REDACTED], [REDACTED], [REDACTED]

1048-1

- B. THE S/I TAKE WAS DEFILMED DIRECTLY FROM THE BUCKET DUE TO INABILITY TO REMOVE UNIT FROM CAPSULE. EVIDENTLY, THE KNURLED RETAINERS, WHICH SECURE THE UNIT IN PLACE, WERE TIGHTENED TOO MUCH. [REDACTED] PERSONNEL BROKE TWO PINS ATTEMPTING TO LOOSEN KNURLED RETAINERS, ALSO HOLES IN KNURLED RETAINERS WERE DAMAGED BEFORE IT WAS DECIDED TO ABANDON IDEA OF REMOVING UNIT.
- C. [REDACTED] PERSONNEL WERE UNABLE TO SEPARATE ONE DEUTSCH PLUG FROM CAPSULE COVER. APER ATTEMPTING TO RELEASE SPRING LOADED PLUG FOR ABOUT 20 TO 30 MINUTES, CABLE WAS CUT SO THAT DEFILMING COULD START WITHOUT FURTHER DELAY. ATTACHED TO CABLE LACING IS IDENTIFICATION W2 P6 ON A NON-METALLIC TAG.
- D. ALL PARTS, AND SEVERED CABLE ENDS ARE INSIDE CAPSULE FOR YOUR ANALYSIS.

~~TOP SECRET~~

BT

Declassified and Released by the N R C  
In Accordance with E. O. 12958  
on NOV 26 1997