

NUMBER AND INDEX LAMP ARE BLOOMED AS - IN 1038-1.

- (2) OPERATIONAL THROUGHOUT. THE CAMERA NUMBER AND INDEX LAMP ARE BLOOMED AS IN 1038-1
- 3. (1) OPERATIONAL THROUGHOUT.
 - (2) OPERATIONAL THROUGHOUT
- F. (1) NONE NOTED
 - (2) NONE NOTED.
- G. (1) OPERATIONAL THROUGHOUT. NO VEILING NOTED.
- (2) OPERATIONAL THROUGHOUT. VEILING OF THE STARBOARD HORIZON CAMERA WAS NOTED A I THE BEGINNING OF THE MISSION. A GRADUAL CLEARING WAS NOTED STARTING ON PASS 86D. THE IMAGERY WAS CLEAR AND SHARP AT THE END OF THE MISSION.

H. OPERATIONAL THROUGHOUT THE MISSION. RESEAU NUMBER 188. APPROXIMATELY 20 PERCENT OF EACH STELLAR FORMAT IS AFFACTED BY FLARE, STELLAR IMAGES CAN BE DETECTED IN THE FLARED AREAS. THREF SMALL FLARED AREAS AROUND THE FORMAT PERIMETER ARE PRESENT THOUGHOUT THE STELLAR RECOD. THEY DO NOT AFFECT THE STELLAR FIELD. THE LAST 71 FRAMES. CONTAIN A FINE PLUS DENSITY LINE, PARRALLEL TO THE MAJOR AXIS OF THE FILM, BETWEEN THE CORRELATION LAMP AND THE FORMAT EDGE.

7 0 P 6 E 0 P F T

APPROXIMILY 10 STELLAR IMAGES CAN BE DETECTED IN EACH EXPOSURE. THEY APPEAR ELONGATED RATHER THAN POINT TYPE IMAGES. FRAMES 4 AND 16 ARE DOUBLE EXPOSURES. I. CPERATIONAL THROUGHOUT. RESEAU NUMBER 111. SMALL CRESCENT SHAPED FOG PATTERNS. ARE PRESENT INTERMITTENTLY ALONG THE EDGE OPPOSITE THE CORRELATION LAMP. THEY DO NOT ENTER THE IMAGERY AND ARE CONFINED TO THE BORDER AREA. THE IMAGE QUALITY IS GOOD AND COMPARABLE TO THAT ATTAINED IN RECENT MISSIONS OF THIS SYSTEM. FRAMES 4 AND 16 ARE DOUBLE EXPOSED. J. (1) THERE IS FOG PRESENT ON FRAME 5 OF ALL CAMERA OPRATIONS. THIS FOG PATTERN IS IDENTICAL TO THAT DESCRIBED FOR 1038-1. THE DENSITY OF THE FOG VARIES WITH THE DURATION OF CAMERA OFF PERIODS.

- 72) THERE IS FOG PRESENT ON THE FIRST, FIFTH AND SECOND TO LAST FRAME OF MOST CAMERA OPERATINS. THE DENSITY OF THESE PATTERNS IS MINOR AND VIARIES WITH THE DURATION OF CAMERA OFF PERIODS.
 - (3) NONE
 - (4) NONE
- K. (I) NONE NOTED.
- (2) DENDRITIC FOG PATTERNS RESULTING FROM STATIC DISCHARGES ARE PRESENT ALONG BOTH

I O P C E O R E T

FILM EDGES INTERMITTENTLY THROUGHOUT
THE MISSION. THEY AREGENERALLY CONFINED TO THE
BORDERS BUT IN SOME CASES THEY EXTEND INTO THE FORMAT
AND DEGRADE THE IMAGERY.

- (3) NONE
- (4) NONE
- L. (1) THIN 5 PER ENT, MEDIUM 50 PERCENT, HEAVY 45 PERCENT
 - (2) THIN 5 PERCENT, MEDIUM 50 PERCENT, HEAVY 45 PERCENT
 - (3) ADEQUATE FOR THE DETECTION OF STELLAR IMAGES.
 - (4) THIN 10 PERCENT MEDIUM 65 PERCENT HEAVY 25 PERCENT
- M. (1). LOW 35 PERCENT, MEDIUM 50 PERCENT, KIGH 15 PERCENT
 - (2). LOW 35 PERCENT, MEDIUM 45 PERCENT, HIGH 20 PERCENT
 - (3). ADEQUATE FOR THE DETECTION OF STELLAR IMAGES.
 - (4). LOW 30 PERCENT, MEDIUM 60 PERCENT, HIGH 10 PERCENT
- N. (1). COMPARABLE TO 1038-1
- (2). SLIGHTLY BETTER THAN THE FORWARD. COMPARABLE TO 1038-1. MIP 80
- O. (1) RAIL SCRATCHES ARE PRESENT ON BOTH FILM EDGES THROUGHOUT THE MISSION. AN EMULSION SCRATCH APPROXIMATELY ONE INCH LONG DIRECTLY UNDER THE CAMERA NUMBER IS PRESENT INTERMITTENTLY THROUGHOUT THE MISSION. IT APPEARS ABOUT ONE SIXTEENTH OF AN INCH INTO THE FORMAT FROM THE BINARY EDGE OF THE FILM. OTHER. VERY FINE EMULSION SCRATCHES APPEAR IN

VARIOUS PARTS OF THE IMAGED FORMAT, INTERMITTENTLY
THROUGHOUT THE MISSION. EXAMPLE PASS DIDO

VERY FINE MINUS DENSITY STREAKS, PARRALLEL TO
THE MAJOR AXIS OF THE FILM ARE PRESENT. ON

PASSES D74 AND D154. THE FORMAT EDGE
ALONG THE CAMERA NUMBER EDGE OF THE FILM IS

RAGGED FROM THE TAKE UP END OF EACH FRAME
TO THE SECOND SHRINKAGE MARKER. MANUFACTURING

SPLICES ARE PRESENT ON FRAME 23 PASS D86, FRAME
30 PASS D125, AND FRAME 34 PASS D137.

(2). RAIL SCRATCHES ARE PRESENT ON BOTH FILM EDGES THROUGHOUT THE MISSION. THE SCRATCH NUMBER THE CAMERA NUMBER DESCRIBED FOR THE MASTER CAMERA IS PRESENT ON THE SLAVE CAMERA MATERIAL. IMMEDIATELY FOLLOWING A MANUFACTURING SPLICE IN FRAME 72 PASS D73 A VERY FINE PLUS DENSITY LINE APPEARS ABOUT ONE QUARTER INCH INTO THE FORMAT FROM THE CAMERA NUMBER EDGE OF THE MATERIAL. IT CONTINUES THROUGH THE MAIN CAMERA FORMAT. THE HORIZON FORMAT, AND THE UNEXPOSED AREAS BETWEEN FRAMES AND GRADUALLY BECOMES LESS DENSE UNTIL IT DISSIPATES APPROXIMATELY HALF WAY THROUGH THE MISSION. THE CAMERA NUMBER EDGE OF THE MATERIAL DISPLAYS A RAGGED FORMAT EDGE FROM THE TAKE UP

7 0 P - C E C R E T -

END OF EACH FRAME TO THE SECOND SHRINKAGE
MARKER. THE LAST FEW FEET HAVE THE USUAL
PINHOLES. GAUGES AND SCRATCHES ASSOCIATED WITH
FILM DEPLETION.

- (3). GOOD, EXCEPT FOR PLUS DENIITY LINE DESCRIBED FOR THE SLAVE CAMERA MATERIAL.
 - (4). GOOD.
 - (5) a GOOD.
- P. (1). (-). 8035 FEET (:). STELLAR, 50 FEET (?). 8946 FEET (D). INDEX 102 FEET
 - (2). (A). 3039 FRAMES (C) 468 FRAMES
 - (B). 3034 FRAMES (D) 468 FRAMES
- Q. 28 JANUARY 1967
- R. REMARKS:
- (1) THE PERCENTAGE OF FILM PROCESSED AT EACH LEVEL OF DEVELOPMENT WAS:

PRIMARY INTERMEDIATE FULL TRANSITION

FORWARD 0 10 81 9

AFT 0 24 70 6

TOFSECRET TOR 391916Z FEB 67

7 6 P S E C P E T