

DATE

2 JUL 1967

~~TOP SECRET~~

1	
2	10 1400029669
3	11
4	12
5	13
6	14
7	15
8	16

TO :
FROM :
ACTION:
INFO :

[REDACTED]

TO ~~TOP SECRET~~ INFO 021120Z CITE [REDACTED] CITE [REDACTED]

PRIORITY [REDACTED] INFO PRIORITY [REDACTED]

[REDACTED]

[REDACTED]

- A. 1042-2
- B. SATISFACTORY - INTERIOR OF CAPSULE DRY; HOWEVER OUTER WRAPS OF PAYLOAD ARE TANGLED AND STUCK TOGETHER.
- C. C-141 40648
- D. 02/0815Z MOFFETT WAS
- E. CAPSULE WAS RETURNED TO [REDACTED] TO FACILITATE INVESTIGATION OF RECOVERY ANOMOLY. BECAUSE OF PAYLOAD WRAPPING AND STICKING IT WAS DECIDED TO RETURN THE ENTIRE CAPSULE TO [REDACTED] FOR DEFILMING.

ACTION TAKEN AT [REDACTED] IS AS FOLLOWS

- 1. MAIN HARNESS PLUG ON CAPSULE COVER IS DISCONNECTED.
- 2. ALL CAPSULE COVER PLUGS HAVE BEEN DISCONNECTED.
- 3. BATTERY IS DISCONNECTED AND CAPPED.

NO FURTHER PLUG DISCONNECTION IS REQUIRED AT [REDACTED] TO REMOVE CAPSULE COVER


NO ELECTRICAL CONNECTIONS TO THE TAKEUPS HAVE BEEN REMOVED.

REQUEST CAPSULE BE RETURNED TO [REDACTED] ASAP FOLLOWING DEFILMING FOR EVALUATION.

~~TOP SECRET~~ TOR 021200Z JUN 67
Declassified and Released by the NRO

In Accordance with E. O. 12958
on NOV 26 1997

~~TOP SECRET~~



REPRODUCTION BY OTHER THAN THE ISSUING OFFICE IS PROHIBITED. COPY NO.