

WE UNDERSTAND THAT THE NO-GO CAUSE FOR MISSION 9011
IS THE FACT THAT THE RECOVERY CAPSULE TELEMETRY IS UNREADABLE.
THIS CONDITION WOULD MAKE IT IMPOSSIBLE TO OBTAIN DATA ON THE
CAPSULE FUNCTIONS DURING THE RE-ENTRY - RECOVERY SEQUENCE. THE
MISSION 9011 CAPSULE IS THE FIRST MK IV CAPSULE TO BE FLOWN.

PERSONNEL AT LAUNCH BASE ARE EVALUATING THE TELEMETRY PROBLEM AT THIS TIME. AS SOON AS WE HAVE ADDITIONAL INFORMATION BEARING ON THE RESCHEDULE OF MISSION 9011, WE WILL PASS IT ON TO YOU IMMEDIATELY.

