## 0 P S E C R E T 281916Z

CORONA-J

ATTN:

FROM: WEBR

DO NOT UNDERSTAND CONCERN OVER ACTIONS TAKEN J-3 AFTER ABORTIVE LAUNCH ATTEMPT. WHEN DECISION WAS FINALLY MADE TO RETURN INSTRUMENT TO L-BUILDING INSPECT FOR WATER DAMA AND DRY OUT AS SOON AS POSSIBLE, I INSTRUCTED AP TO HAVE L-BLDE PERSONNEL CUT AND REMOVE FILM THREADED THROUGH ROLLERS AND RAILS IF WATER WAS PRESENT. I DID NOT WANT FILM STICKING TO ROLLERS, ETC. SINCE I HAD PREVIOUSLY ACCEPTED J-3 FOR GOVERNMENT, IT WAS NO LONGER BEEN IN POSITION TO RESPOND WITH THE SWIFTNESS I DEEMED NECESSARY, THEY WOULD CERTAINLY HAVE HAD REPRESENTATION THERE. PERSONNEL DID NOT ARRIVE BASE UNTIL SEVERAL HOURS AFTER J-3 HAD BEEN RETURNED TO L-BUILDING. HAVING CONSIDERABLE KNOWLEDGE OF PROFICIENCY OF L-BUILDING PERSONNEL I WAS CONFIDENT THEY COULD DO WORK REQUESTED WITHOUT FURTHER DAMAGE TO INSTRUMENT. SUBSEQUENT INSPECTION BY PERSONNEL CONFIRMS NO DANAGE DUE TO FILM REMOVAL TROUBANK

I HAVE TALKED TO LOCALLY AND INFORMED THEN THAT JOSE WILL BE RETURNED TO CONTRACTOR FOR REWORK. THEY HAVE BEEN ADVISED TO ESTIMATE COST ON BASIS OF INSTRUMENT CONDITION AS THEY FIND

IT THEN. BETWEEN TIME I SIGNED OF FARM 250 AND THE FIND INSTRUMENT BACK (27 JAN 64) J-3 VAS A GOVERNMENT LIABILITY.

COULD HAVE BROUGHT MATTER UP AT SE MEETING WITHOUT BY REMINDING COMBATANTS THAT AT THE TIME J-3 BELONGED TO GOVERNMENT A. DO NOT KNOW WHY IT TOOK PERSONNEL SO LONG TO GET DOWN TO I -BUILDING. DID GO ON TUESDAY 22 AP. ARRIVED BEFORE IF ( THEY MIGHT DO WELL TO ASK WHERE THEIR BASE RESIDENT REPRESENTATIVE WAS DURING THIS TIME. FRANKLY, IT DID NOT OCCUR TO HE THAT HE WOULD NOT BE THERE. I WOULD HAVE ISSUED SAME INSTRUCTIONS, SINCE LOSS OF ACTIVE SE ELEMENT AT AP INFORMATION CHANNELS HAVE BECOME SOMEWHAT CONSTIPATED. CREDIT THIS FOR LEGI OF TIMELY RESPONSE BY THOSE WHO MUST DEPEND UPON OTHERS FOR INFO

INTEND TO DISCUSS THIS MORE FULL

THIS INCLUDES ME. Subsequent Message.

Declassified and Released by the NRC

MATION.

n Accordance with € 0.12958

NOV 2 6 1997