

- 1. RECHECK BY PAYLOAD PEOPLE OF PASS 15 RECORDS INDICATE PASS 15 REAL TIME READOUT WAS IN ERROR AND CAMERA OPERATION DID NOT OCCURE ON PASS 15.
- 2. THE T/M POINT WHICH INDICATED WEIGHT OF FILM TRANSFERRED HAS BEEN INACCURATE IN THE PAST. ALSO RECALIBRATION OF THE CUTUPS ASSOCIATED WITH THE WEIGHT TRANSFERRED INDICATE THAT THE READING WAS CLOSE TO MAX WEIGHT CARRIED.
- 3. MAJORITY OF EVIDENCE NOW INDICATES ALL FILM WAS CONSUMMED AS SCHEDULED. THIS BASED ON ABOVE DATA PLUS 6 OTHER T/M POINTS ON PASS 15.

