

~~SECRET~~



13 JUL 65 15 23 Z

[REDACTED]

~~SECRET~~ 122115Z

[REDACTED] INFO [REDACTED] CITE [REDACTED]

CORONA

SUBJECT MISSION 1020-1

REF [REDACTED]

1. THE EDGE FOG ON THE MASTER CAMERA SUPPLY SPOOL EXTENDING 1/16 INCHES ALONG ONE EDGE INDICATED IN REF WAS SIMILARLY NOTED ON P-2 SAMPLE AND ON FIRST SECTION OF THE MASTER MISSION ROLL EXTENDING TO THE FIRST MANUFACTURING SPLICE.

2. THIS DEFECT WAS INTRODUCED DURING THE MANUFACTURE OF THE FLIGHT FILM.

3. TESTING PROCEDURES HAVE BEEN THOROUGHLY REVIEWED WITH ALL OPERATORS. THE IMPORTANCE OF COMPLETE ADHERENCE TO EACH STEP IN PROVIDING HIGHEST POSSIBLE QUALITY FLIGHT FILM HAS BEEN STRONGLY EMPHASIZED.

~~SECRET~~

END OF MSG

Declassified and Released by the N R O

In Accordance with E. O. 12958

on NOV 26 1997

~~SECRET~~