

~~SECRET~~

BIF 007-0607-75

HANDLE VIA BYEMAN
CONTROL SYSTEM ONLYS³ PROGRAM HIGHLIGHTS

1. PROGRAM DEFINITION PHASE

- SYSTEM CONFIGURATION STUDIES
- OPTICAL DESIGN STUDIES
- TECHNICAL RISK EVALUATION PLANS
- EQUIPPED PHOTODETECTOR TEST LABORATORY
- ERROR BUDGET ANALYSIS

2. RISK EVALUATION PHASE

- INTERFACE MEETING WITH SBAC
- SV-9 ON-ORBIT CALIBRATION TESTS
- FRAME DEFORMATION TESTS
- MIDSECTION DEFORMATION TESTS
- FOCAL PLANE COOLER PERFORMANCE TESTS
- PHOTODETECTOR PERFORMANCE TESTS

/ 10/13/75 WEK

ENVIRONMENT EFFECTS (CONT'D)

4. CONCLUSION

- ENVIRONMENTAL ERRORS COMBINE AS FOLLOWS:

<u>ROLL</u>	<u>PITCH</u>	<u>YAW</u>
3.3 SEC	4.0 SEC	4.4 SEC

- ALL ERROR CATEGORIES COMBINE AS FOLLOWS:


	<u>ROLL</u>	<u>PITCH</u>	<u>YAW</u>
STELLAR SENSOR POINTING ERROR	1.4 SEC	1.8 SEC	1.3 SEC
INTERLOCK CALIBRATION ERROR	1.9 SEC	2.2 SEC	1.8 SEC
ENVIRONMENTAL STABILITY	3.3 SEC	4.0 SEC	4.4 SEC
	<u> </u>	<u> </u>	<u> </u>
RSS	4.1 SEC	4.9 SEC	4.9 SEC

- PRACTICAL SOLUTIONS HAVE BEEN FOUND.
- VERIFICATION TESTS SUPPORT ERROR BUDGET.

10/13/75 WEK

007-0007-75

TEST SETUP IN ENVIRONMENTAL LAB PIT




BIF 007-0607-75

~~TOP SECRET~~

FORN DISSEM
CONTROL SYSTEM ONLY

ENVIRONMENT EFFECTS (CONT'D)

VEHICLE DISTORTION



TCA TWISTS
WHEN VEHICLE
TWISTS

FIRST CHAMBER A
TEST VERIFIED
MOTION


FORWARD
END

10/13/75 WEX

~~TOP SECRET~~
HANDLE VIA BYEMAN
CONTROL SYSTEM ONLY

BIF 007-0607-75

SIDE-TO-SIDE TEMPERATURE DIFFERENCE ON TCA FRAME FOR SELECTED REV. OF SV-4




REV. NUMBER 359 ($\beta = 31^{\circ}$)

~~TOP SECRET~~

BIF 007-0607-75

HANDLE VIA HYEMAN
CONTROL SYSTEM ONLY

SIDE-TO-SIDE TEMPERATURE DIFFERENCE ON TCA FRAME FOR SELECTED REV. OF SV-4



REV. NUMBER 1041 ($\beta = 33^\circ$)

2/12/75 LK

HANDLE VIA BYEMAN
CONTROL SYSTEM ONLY

POINTING ERRORS DUE TO ENVIRONMENT EFFECTS

<u>ERROR SOURCE</u>	<u>POINTING ERROR - ARC SECOND (1σ)</u>		
	<u>ROLL</u>	<u>PITCH</u>	<u>YAW</u>
ALIGNMENT CHANGE OF PAN CAMERA LOS TO S ³ SENSOR MTS. DUE TO THERMAL ENVIRONMENT			
SIDE TO SIDE GRADIENT IN TCA (ΔT = 2 ⁰ F)	1.7	2.0	3.5
FRONT TO REAR GRADIENT IN TCA (ΔT = 3 ⁰ F)	0.6	0.8	1.2
TOP TO BOTTOM GRADIENT IN TCA (ΔT = 0.2 ⁰ F)	0.6	1.9	-
DEFORMATION IN TCA DUE TO VEHICLE DISTORTION	1.5	1.0	-
PRIMARY MIRROR TILT (ΔT = 0.5 ⁰ F, METERING RODS)	0.4	0.4	-
FOLD FLAT TILT (ΔT = 2.0 ⁰ F in TEMP. LEVEL)	-	0.7	0.5
RSS ₁	2.5	3.1	3.7

10/16/75 CLK

STELLAR SENSOR POINTING ERROR

ERROR SOURCE	POINTING ERROR - ARC-SECONDS* (1σ) (S ³ CAMERA COORDINATES)	
	Y _A	Z _A
CENTROIDING ERROR	2.0	2.0
DETECTOR LOCATION ERROR	1.6	1.6
RESIDUAL OPTICAL DISTORTION	1.6	1.6
FOCAL PLANE RESIDUAL THERMAL ERROR	1.0	1.0
STAR CATALOG UNCERTAINTY	0.5	0.5
POINTING ERROR/STAR	3.2	3.2
FOR 9 DETECTIONS/FIELD	$e = \frac{e_0}{\sqrt{N}}$	
ATTITUDE CONTROL SYSTEM	1.2	1.2
S ³ POINTING ERROR	1.6	1.6
POINTING ERROR TRANSFERRED TO TCA COORD. SYSTEM USING 2-S ³ SENSORS:		
ROLL	1.4	ARC-SECONDS - 1σ
PITCH	1.8	
YAW	1.3	


* 253 mm F.L. : 1 micron ≈ 0.8 arc-second.

INTERLOCK CALIBRATION ERROR
STELLAR/PAN CAMERAS


<u>ERROR SOURCE</u>	<u>POINTING ERROR - ARC SECONDS (1σ)</u>		
	<u>ROLL</u>	<u>PITCH</u>	<u>YAW</u>
STELLAR SENSOR POINTING ERROR	1.4	1.8	1.3
PAN PHOTO MENSURATION ERROR	0.8	0.9	1.0
ANGULAR VIBRATION OF TCA	1.0	1.0	1.0
SVT CORRELATION	-	0.3	-
RSS	1.9	2.2	1.9

10/16/75 LK


~~SECRET~~
HANDLE VIA BYEMAN
CONTROL SYSTEM ONLY



CASE 2A - Z-AXIS DISPLACEMENT OF FORWARD FRAME MEMBER AT CENTER OF COMPLIANCE. (NO TWIST ABOUT THE X-AXIS.)




CASE 2B - Z-AXIS DISPLACEMENT OF 0.004 INCH AT PORT PITCH LINK ANCHOR. (CAUSES 1.5 SEC TWIST ABOUT X-AXIS.)



CASE 2C - Z-AXIS DISPLACEMENT OF 0.004 INCH AT STARBOARD PITCH LINK ANCHOR. (CAUSES 0.9 SEC TWIST ABOUT THE Y-AXIS.)


SCHEMATIC REPRESENTATION OF MODIFIED PITCH LINK

SIMULATED AND TESTED
IN CHAMBER A.
NO EFFECT ON PHOTO-
GRAPHIC PERFORMANCE.





10/13/75 WEK

FRAME BENDING TEST DIAL INDICATOR DATA
HEAT SYMMETRICALLY APPLIED INTO B-SIDE FRAME



A-SIDE BEAM - OUTSIDE SKIN




Q_{IN} FWD BEAM
○ DIAL INDICATOR

~~Hx SECRET~~

32003
C05137240

S³ CAMERA SYSTEM



Approved for Release: 2025/06/18 C05137240

Approved for Release: 2025/06/18 C05137240


~~Hx SECRET~~

~~TOP SECRET~~

BIF 007-0607-75

HANDLE VIA BYEMAN
CONTROL SYSTEM ONLY

S³ OPTICAL AXES



ERROR CATEGORIES

1. STELLAR SENSOR POINTING ERROR
2. INTERLOCK CALIBRATION ERROR
3. ENVIRONMENTAL STABILITY ERROR


10/13/75 WEK

75-719

30496

STAR IMAGES

50 MICRONS



SPURIOUS
ARTIFACTS

BOSS # 16551
M 4.3

ALPHA CRUCIS
M 1.6, 2.1

76-718

30495

STAR IMAGES



ALPHA CENTAURI

M 0.3, 1.7



CANOPUS

M - 0.9

6/11-12/75 IR