

~~SECRET~~

## Memorandum

To: Code 5430

From: 5435

Subj: Status of Mission 7104 payloads:

1. Recent messages relayed from DirNavSecGru Headquarters and originating in [ ] have disclosed a rapid deterioration of two of the Mission 7104 Payloads, 7104B and 7104D (NRL # 142 and # 144). On rev 6693, 94 and 97, [ ] observed TM segments # 6 and 7 off lower band edge (Should indicate excessive negative voltage and inadequate Positive voltage). Data Link Commands do NOT get any results from Payload.
2. 7104D (NRL #144) beginning with Rev# 6641 have shown continued Telemetry malfunction...sounds just like Noise instead of the segment switched tones. Data Link Teletales are observed along with data but no positive proof of just which commands have been accepted; therefore considerable possibility of data ambiguity as to which bands have been turned on.
3. Hybla Valley, observed Pass # 6709 Monday evening; TM records under Study by 5170

~~SECRET~~HANDLE VIA  
BYEMAN  
CONTROL SYSTEM ONLY