

CLASSIFIED MESSAGE

~~TOP SECRET~~  
~~TOP SECRET~~

DATE 2250Z 22 JUL 62

ROUTING	
4	
5	
6	

TO DIRECTOR

FROM [REDACTED]

ACTION OPS (1-2-3-4-5) Declassified and Released by the NRO

INFO S/C (6) In Accordance with E. O. 12958

RU on NOV 26 1997

TOR: 2310Z 22 JUL 62



**OPERATIONAL IMMEDIATE**

[REDACTED]

TO OPIM [REDACTED]

INFO PRITY [REDACTED]

CITE [REDACTED]

[REDACTED]

A. 9039

B. HAVE EXERCISED ALL COMMAND STEPS WITH NO CHANGE IN CAMERA STATUS. T/M INDICATES STEPS ARE OPERATING CORRECTLY. PROBLEM BELIEVED TO BE IN CIRCUIT FROM PROGRAMMER TO CAMERA. NO OPERATE COMMANDS ARE BEING RECEIVED BY CAMERA. HAVE EXERCISED RESET COMMAND WHICH LIFTS AND REPLACES CONTACT BRUSHES WHICH IN TURN ISSUE OPERATE SIGNAL TO CAMERA. (RESET COMMAND WILL ACCOMPLISH THIS EVEN THOUGH CANNOT BE USED TO INDEX PROGRAMMER TAPE). RESULTS ARE NEGATIVE. ABOVE TWO ITEMS ONLY ACTION THAT CAN BE TAKEN. CONCLUSION IS THAT CAMERA SYSTEM CAN NOT BE OPERATED.

IN VIEW OF ABOVE RECOVERY IS PLANNED ON REV 33. HOWEVER, WILL CONTINUE TO EVALUATE T/M AND IF ANY INDICATION CAMERA OPERATION RECOVERY WILL BE DELAYED.

END OF MESSAGE

~~TOP SECRET~~  
~~TOP SECRET~~

GROUP 1  
EXCLUDED FROM AUTOMATIC  
DOWNGRADING AND  
DECLASSIFICATION  
REPRODUCTION BY OTHER THAN THE ISSUING OFFICE IS PROHIBITED. Copy No.

REPRODUCTION BY OTHER THAN THE ISSUING OFFICE IS PROHIBITED.