

~~TOP SECRET~~



~~TOP SECRET~~ 120917Z

IMMEDIATE [REDACTED] CITE [REDACTED]
[REDACTED]

REF MSN 1011-2

1. DUE TO LOW VOLTAGE, COMMAND BEACON NOT ACQUIRED ON REV 101. ATTEMPTED COMMANDS IN BLIND BUT UNSUCCESSFUL. RESULT IS THAT REV 101D TAKEN IN PROGRAM 4 INSTEAD OF DESIRED PROGRAM 9.

2. ON REV 102 COMMAND LOCK-ON WAS NEVER ACCOMPLISHED. COMMANDS WERE SENT BUT WERE NOT EFFECTIVE. THEREFORE REV 102D ALSO TAKEN IN PROGRAM 4 INSTEAD OF DESIRED PROGRAM 9.

3. UNLESS COMMAND CAPABILITY REGAINED REMAINDER OF MISSION WILL BE ACCOMPLISHED IN PROGRAM AND FILM WILL BE EXHAUSTED ON REV 110. WILL NOT ATTEMPT ANY MORE COMMANDING IN BLIND UNTIL REV 105 FOR FEAR THAT MAY END UP IN PROGRAM LESS DESIRABLE THAN PROGRAM 4. 105 MUST BE IN PROGRAMS 1 OR 2 TO GET ANYTHING. REVS 108 AND 109 CANNOT BE DENIED SINCE CANNOT TURN INSTRUMENT OFF.

4. WILL KEEP YOU PROMPTLY ADVISED OF STATUS.

~~TOP SECRET~~

~~TOP SECRET~~

Declassified and Released by the NRC

in Accordance with E. O. 12958

on NOV 4 1991