



~~TOP SECRET~~ 061738Z

IMMEDIATE [REDACTED] INFO PRIORITY [REDACTED] CITE [REDACTED]

[REDACTED]

A. 1013-1

B. (1) 2970 CYCLES THRU REV 58

(2) 3007 CYCLES THRU REV 58

(3) N/A

C. FOOTAGE POTS HAVE SHOWED NO ADVANCE SINCE REV 56 AT WHICH TIME THEY READ 2266 CYCLES ON MASTER AND 2273 CYCLES ON SLAVE.

PESSIMISTIC OUTLOOK IS THAT THERE HAS BEEN A FAILURE IN THE TAKE-UP ASSEMBLY RESULTING IN DISABLING BOTH INSTRUMENTS ALMOST SIMUL-

TANEOUSLY. OPTIMISTIC OUTLOOK IS THE INSTRUMENTATION

IN INSTRUMENTATION AND SYSTEM IS OPERATING NORMALLY.

IN EITHER CASE THE OPERATIONAL PROCEDURES FROM HERE TO REV 65

WILL REMAIN SAME. IN ORDER THAT MAY HAVE SUFFICIENT FILM ROOM

TO RUN ENGINEERING OPERATION ON REV 63 AM TAKING REV 61 IN PROGRAM

3, DENYING REV 62, AND TAKING REV 63 IN PROGRAM 6. WILL BE ABLE

TO TELL CONDITION OF INSTRUMENTS ON REV 63.

~~TOP SECRET~~

Declassified and Released by the NRO

In Accordance with E. O. 12958

on NOV 26 1997