


~~TOP SECRET~~



Apr 29 00 10 56

[REDACTED]

~~TOP SECRET~~ 282328Z

[REDACTED] INFO [REDACTED] CITE [REDACTED]

[REDACTED]

CORONA

REFERENCE: (A) 1831

(B) [REDACTED]

1. ON REV 14 COMMAND DIFFICULTY WAS EXPERIENCED AT [REDACTED] IN THAT A CAMERA OPERATION WAS OBTAINED THAT WAS NOT PROGRAMMED (21 CYCLES ON PROGRAM 7, STEREO, 3 QUADRANT, BETWEEN 20 NORTH AND 23 NORTH).

THE DIFFICULTY IN COMMANDING WAS THE RESULT OF A PROCEDURAL ERROR.

THE STATION FAILED TO UPDATE THE PREPASS TAPE WITH THE ACQUISITION MESSAGE, AND CONSEQUENTLY WAS SOME 20 SECONDS OUT OF SYNC WITH THE VEHICLE. ALL STATIONS HAVE BEEN ADMONISHED TO USE CORRECT PLOCEDURES IN THE FUTURE.

~~TOP SECRET~~

END OF MESSAGE

Declassified and Released by the NRO
In Accordance with E. O. 12958
on NOV 26 1997

~~TOP SECRET~~