

CLASSIFIED MESSAGE

~~TOP SECRET~~

1	9	140061519
2	10	
3	11	
4	12	
5	13	
6	14	
7	15	
8	16	

DATE

TO :

FROM :

ACTION:

INFO :

on NOV 26 1997

[REDACTED]

10 R

TO

INFO

CITE

~~TOP SECRET~~ 270010Z JAN 68 CITE [REDACTED]

IMMEDIATE [REDACTED] INFO PRIORITY [REDACTED]

REF A. 1045-1

B. [REDACTED]
C. [REDACTED]

1. REPRESENTATIVES FROM [REDACTED] AND [REDACTED] HAVE REVIEWED THE CIRCUMSTANCES OF THE BIAS ERROR AND HAVE ESTABLISHED THE FOLLOWING PROCEDURES TO PRECLUDE RE OCCURRENCE.

A. A NEW STANDARD FORMAT WILL BE USED BY ALL CONCERNED FOR REQUESTING AND ACCOMPLISHING TIMER BIASING. (I.E. "BIAS THE TIMER SO THAT SUBCYCLE START OCCURS BLANK SECONDS BEFORE OR AFTER CROSSING THE ASCENDING NODE").

B. THIS INFORMATION WILL BE SUPPLIED TO THE FTFD [REDACTED] BY HARD COPY.

C. AFTER PREPARATION OF OPERATIONS INSTRUCTION BY FTFD AND PRIOR TO INPUT TO THE TEST CONTROLLER, COORDINATION WILL BE MADE WITH THE RESIDENT OFFICE DUTY OFFICER IN THE SAME MANNER AS PREPASS COMMANDING COORDINATION.

~~TOP SECRET~~

GROUP 1
EXCLUDED FROM AUTOMATIC
DOWNGRADING AND
DECLASSIFICATION

REPRODUCTION BY OTHER THAN THE ISSUING OFFICE IS PROHIBITED. COPY NO.

~~TOP SECRET~~

PAGE 2

2. THIS MESSAGE HAS BEEN COORDINATED WITH MURPHY AND [REDACTED]

~~TOP SECRET~~ TOR: 270119Z JAN 68

~~TOP SECRET~~