

ADIC PASS TO JESSUP AT WHITE HOUSE AND MR. ODUM AT STATE DEPT.

RECOVERY BUCKET (SRV) 2 OF CORONA/J MISSION 1019 FAILED TO

RESPOND PROPERLY TO RECOVERY TASKING 8 MAY 1965. TELEMETRY CONFIRMS

SEPARATION FROM AGENA HOUSING CAMERA PAYLOAD, BUT SRV, WHICH CONTAINS


EXPOSED FILM, THROWN INTO ERATIC 600 N.M. APOGEE 85 N.M. PEROGEE

ORBIT. ORBITAL DECAY ESTIMATED 30-40 DAYS. SPADATS HAS BEEN TASKED TO

MONITOR.

NORMAL RECOVERY SAFETY FEATURE SHOULD HAVE CAUSED SEPARATION OF SRV ABLATIVE HEAT SHIELD, HOWEVER TELEMETRY STILL BEING EXAMINED FOR CONFIRMATION.

END OF MSG



(b)(3)

REPRODUCTION BY OTHER THAN THE ISSUING OFFICE IS PROHIBITED. COPY NO.