

8

ITN 0849
121217 PP YYY RUXORAA0071 1341508 00013-XXXX--RUXPDAA.
ZNY XXXXX YYY ZNM
P 141505Z
BT
XXXXX

~~SECRET~~
~~SECRET~~
HANDLE VIA BYEMAN
CONTROL SYSTEM
0903

~~SECRET~~ 141505Z MAY 82 CITE [REDACTED] 0071
PRIORITY [REDACTED] INFO PRIORITY [REDACTED]
HANDLE VIA BYEMAN CHANNELS ONLY

GAMBIT
ATTN: [REDACTED]
INFO: [REDACTED]
FROM: [REDACTED]

REF: CONVERSATION [REDACTED] R. STOWE [REDACTED]
1. PER REFERENCE: SINCE A HIGHER THAN NORMAL PROBABILITY THAT
4352-2 SRV MAY BE A WATER RECOVER, SUGGEST PERSONNEL INVOLVED
IN RECOVERY EFFORTS BE REMINDED OF THE FOLLOWING:
SHOULD THE SRV HAVE BEEN DAMAGED ALLOWING WATER AND/OR
LIGHT TO ENTER, THE WATER SHOULD BE DRAINED THROUGH THE
DAMAGE HOLE, IF POSSIBLE, AND THE SRV PLACED IN A
LIGHT TIGHT POLYETHELENE BAG AS SOON AS POSSIBLE. THE
UNIT SHOULD BE HANDLED FOLLOWING NORMAL PROCEDURES.

REVW: 14 MAY 2002
~~SECRET~~
BT
#0071

NNNN

~~SECRET~~
~~SECRET~~
HANDLE VIA BYEMAN
CONTROL SYSTEM

NRO APPROVED FOR RELEASE
DECLASSIFIED BY: C/IART
DECLASSIFIED ON: 10 JANUARY 2013