

~~TOP SECRET~~

14 000222780

~~TOP SECRET~~ 182213Z

IMMEDIATE [REDACTED] INFO PRIORITY [REDACTED] CITE [REDACTED]
[REDACTED]

REF MSN 1012-1

BECAUSE OF THE DANGER OF LOSING BEACON ALTOGETHER, INTRODUCING DEACTIVATION, AND/OR INADVERTENTLY SETTING UP CAMERA COMMAND STRUCTURE MORE UNDESIRABLE THAN PRESENT CONDITION, ALL COMMANDING WILL BE SUSPENDED UNTIL BEACON CONDITION IMPROVES TO POINT WHERE IT CAN BE RELIABLE. AT PRESENT CAMERA IS STILL IN PROGRAM SERVICE. BE AS GOOD AS ANY FOR CONDITION. TIMER THUS FAR IS HOLDING EVENTS WITHIN PROGRAM PADS. DUE TO REV 10 ATTEMPTS TO OPERATE NORMALLY, PROGRAMMER IS NOW STEPPING DOWN IN INTERMIX MODE, REV 19 WILL BE "OFF". REV 17 WILL BE IN "OFF" MODE AS DESIRED. ALL OTHERS WILL BE "ON". FOR YOUR FILM ACCOUNTING, FOLLOWING IS RECAP OF REVS TAKEN THUS FAR, ALL IN PROG 4: 1, 2, 3, 4, 5, 6, 7, 8, 9, 14, 15, 19.

~~TOP SECRET~~

Declassified and Released by the NRO

In Accordance with E. O. 12958

on NOV 26 1997

~~TOP SECRET~~