

~~TOP SECRET~~

14 000223080

~~TOP SECRET~~ 070330Z

PRIORITY [REDACTED] INFO PRIORITY [REDACTED] CITE [REDACTED]

REF MSN 1013-1

1. IN ORDER THAT EVERY POSSIBLE CLUE TO FAILURE OF INSTRUMENTS ON REF MISSION MAY BE PRESERVED FOLLOWING PROCEDURE REQUESTED OF [REDACTED]

A. AS CLOSELY AS POSSIBLE MONITOR AND INSPECT FILM AS IT UNROLLS FROM TAKE-UP SPOOLS. LOOK FOR FAULTY WRAP, ANY TENDENCY TO PILE UP ON ONE SIDE OF SPOOL, CRIMPING OF EDGES ETC.

B. DO NOT INSPECT [REDACTED] MATERIAL BEYOND THAT SPLICE IS PREFLIGHT AND LEADER AND HAS NO INTELLIGENCE SIGNIFICANCE. LEAVE THAT MATERIAL UNDISTURBED ON SPOOLS AND RETURN TO [REDACTED] USING SAME SUITCASES IN WHICH DELIVERED.

2. REQUEST [REDACTED] ARRANGE COURIERS FOR RETURN OF SPOOLS TO [REDACTED] IMMEDIATELY [REDACTED] FINISHED DE-SPOOLING OF MISSION TAKE.

~~TOP SECRET~~

Declassified and Released by the NRO

In Accordance with E. O. 12958

on ~~NOV 26 1997~~

~~TOP SECRET~~