

~~SECRET~~

FILE INFO

(When Filled In)

REPRODUCTION PROHIBITED

ACTION	1								
	2								
	3								
	4								
	5								

1052

How that
FW being class
to DISASSEMBLY

~~SECRET~~ 141359Z OCT 69 CITE

PRIORITY INFO

ORONA

REFERENCE:

A FILM TEAR WAS DETECTED IN THE APT CAMERA ORIGINAL MATERIAL DURING THE DEFILMING OPERATION OF MISSION 1052-1. THE TEAR WAS REPAIRED PRIOR TO PROCESSING AND NO FURTHER INCIDENTS WERE EXPERIENCED. SINCE A REPORT CONCERNING THE ANOMALY WAS OMITTED FROM THE REFERENCED CABLE, THE SPECIFICS FOLLOW: A TEAR IS LOCATED AT THE CENTER OF FRAME 43 OF PASS 56. IT EXTENDS INTO THE BINARY FILM EDGE A DISTANCE OF APPROXIMATELY ONE INCH. AN ANGLE OF 65 DEGREES (IN THE SUPPLY DIRECTION) IS FORMED BETWEEN THE TEAR AND THE FILM EDGE. A MANUFACTURING SPLICE IS LOCATED 2.8 FEET FROM THE ANOMALY BETWEEN FRAMES 55 AND 56 OF PASS D56. THE ORIGINAL NEGATIVE OF PASS D56 WILL BE AVAILABLE FOR THE PRT MEETING OF MISSION 1052.

~~SECRET~~

Declassified and Released by the N R C

In Accordance with E. O. 12958

on NOV 26 1997