14 October 1959

MEMORANDUM FOR: Deputy Director (Plans)

are similar.

SUBJECT: Apparent Discrepancies Between 1171, and C Assembly Facilities

1. As volunteered to you briefly on 12 October after the Senior Staff Meeting and now in response to your request, I would offer the following extract from one of our memoranda for the record:

"In reviewing the plant in which the nose comes for Project 1171 are being assembled, it has been noted that great care is taken to create an atmosphere of surgical sterility. This

includes the changing of clothes, complete bathing, surgical garments, face masks, hats, etc. Even a wind tunnel which dries and filters for the complete the complete state of the filters for the complete state of the state of the specious preparation rooms, contrasting sharply with the picture of this sterile, highly controlled environment, it has been noted that the "C" facility has the atmosphere of somewhat less than ideal cleanliness factors with no apparent controls for pressure, highly technical and complex machine assembly plant. It is impossible for us to evaluate the difference in the speciment of the methodologies but there can be little doubt that we are dealing analogous and products. Certainly the 1171 facility is more expensive even though the complexity and technology presented

ARTHUR C. LUMDAHL
Director
Photographic Intelligence Center

Hillion