## SPERET

## DEPARTMENT OF THE AIR FORCE WASHINGTON

Office of the Secretary

11 September 1961

## MEMORANDUM FOR THE SECRETARY OF DEFENSE

ATTENTION: Brig Gen George S. Brown

Military Assistant

Info Cys to: OSD Dep SAFRD SAFMS (3)
OSD Spec Asst SAFFM AFCCS
ODDR&E (Dr. Brown): SAFMA AFCVC
SAFS: SAFLE AFCIN

SAFUS SAFOI AFCVS-DSMG

AFSDC-IN-1K-

SUBJECT: (U) SAMOS Launch Report

- 1. (U) SAMOS III (Atlas 106D/Agena 2120) exploded on pad number 1 at the PMR, Point Arguello Complex at approximately 1529 EDT, 9 Sep 61.
- 2. (S) Preliminary information indicates a malfunction in booster electrical system caused inadvertent engine shutdown approximately one second after lift-off. Missile settled back on pad after lifting approximately 2-3 feet and exploded. Initial pad damage report indicates all plumbing and wiring above ground destroyed; umbilical mast still standing, but structural integrity in doubt; launcher damaged, will probably require replacement; equipment rooms below pad appear to be relatively undamaged; gantry appears undamaged, although gantry crane is damaged slightly; Atlas booster and Agena second stage were completely destroyed. Pad #2 of the launch complex was undamaged. Investigation to determine exact cause of failure is continuing.

O'HIGRADED AT 12 YEAR INTERVALS; OT AUTOMATICALLY DECLASSIFIED DOD DIR. 5200.10

Brigadier General, USAF
Director, Office of Missile
& Satellite Systems

DS 61-4377-A/70:23:2

BECRET

In lest us.