

~~TOP SECRET~~



~~TOP SECRET~~ 290057Z

IMMEDIATE [REDACTED] INFO PRIORITY [REDACTED] CITE [REDACTED]  
[REDACTED]

A. 1005-1

B. BEST DATA AVAILABLE INDICATES THAT "ELECTRICAL OPEN"  
HAS OCCURED IN PYRO DISTRIBUTION PLUG AS RESULT OF SHORT  
OCCURRING ELSEWHERE. SIGNIFICANCE OF THIS IS:

1) NO POWER HAS BEEN OR CAN BE APPLIED TO PYROS THAT EJECT  
CAMERA DOORS.

2) HIGH POSSIBILITY THAT RECOVERY CAN NOT BE ACCOMPLISHED  
BECAUSE OF REQUIREMENT FOR PYRO POWER TO ACCOMPLISH CERTAIN  
RECOVERY EVENTS.

VEHICLE CONDITION OTHER THAN ABOVE IS NORMAL ON REV 16.  
PAYLOAD CONDITION IS AS PREVIOUSLY REPORTED.

C. NCNE

~~TOP SECRET~~

Declassified and Released by the N R C

Accordance with E.O. 12958

NOV 26 1997

DN