

~~TOP SECRET~~



Nov 30 19 20 '63

OPERATIONAL IMMEDIATE

[REDACTED]

PRIORITY

~~TOP SECRET~~ 301657Z

OPIM [REDACTED]

CITE [REDACTED]

[REDACTED] - FLASH REPORT SUBMITTED PRIOR TO [REDACTED]

- A. MISSION 1001-1
- B. PORT HORIZON CAMERA SHUTTER ON FWD CAMERA REMAINED OPEN INTERMITTENTLY CAUSING LOSS OF APPROX. 1000 FRAMES FROM FWD TAKE. THE MALFUNCTION BEGAN ON PASS A-34, CAUSING 80 PERCENT LOSS OF IMAGERY DUE TO HEAVY FOG.
- C. 60 PERCENT OF INDEX CAMERA TAKE IS LOST DUE TO INTERMITTENT SHUTTER PROBLEMS IE: SHUTTER REMAINED OPEN INTERMITTENTLY FOR 2 OR 3 FRAME DURATION.

~~TOP SECRET~~

END OF MESSAGE



Declassified and Released by the N R O

In Accordance with E. O. 12958

on NOV 26 1997

~~TOP SECRET~~

[REDACTED]